

23949

REPORT of SURVEY for REPAIRS.

No. 43 Survey held at Gt Yarmouth Date 13th May 1861
on the S² "Earl Grey" Master W Collins
Tonnage 97 Built at Yarmouth When built 1831
By whom built _____ Owners J Green
Port belonging to Yarmouth Destined Voyage _____
If Surveyed Afloat or in Dry Dock Fellows dry dock

Last Survey, No. 7015 Port Sunderland Classed 10 AE 1
SS. 56 - 60

REPAIRS

In consequence of damage: one deck beam, one lodging knee and six earlings removed with English and French oak, one wale plank on starboard side with Oak, seven planks of main deck with Pine and the ship recaulked throughout.

Present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways	} good	Breasthooks and Stemson	} good	Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings	} good	Timbers of the Frame	} where seen	Masts, Yards, &c.	} In good order
Lower Deck Beams & Fastenings		Keelsons		Sails	
Planksheers	} where seen	Clamps and Shelves	} do	Anchors No. of	} sufficient
Sheerstrakes		Ceiling		Cables	
Topsides	} do	Rudder	} do	Hawsers and Warps	
Wales		Copper		Standing & Running Rigging	
Plank (Bottom) and Counter	do	When put on			

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where seen

This vessel is now in good condition fit for the conveyance of dry and perishable cargoes to and from all parts of the world and is eligible in my opinion to remain as classed

The Amount of Fee.....£ : 10 : - is received by me,

Special..... : : -

Certificate (if required) : 2 : 6

Committee's Minute 24th May 1861

Character assigned R. 1 asterisk

per expenses 10/-

record damage repairs

Mr J. Green Row 31 George Street Gt Yarmouth

© 2021

Lloyd's Register
Foundation

LON 644 - 0204