

REPORT of SURVEY for REPAIRS.

No. 60 Survey held at London Date 16th July 1861
on the Ship "Dartmouth" Master H Davis
Tonnage 433 Built at Dundee When built 1859
By whom built _____ Owners James Bos
Port belonging to London Destined Voyage For Calcutta
If Surveyed Afloat or in Dry Dock James dry dock

Last Survey, No. 2684 Port Dundee Classed 14 A1

REPAIRS

Now done

The yellow metal sheathing stripped off the bottom
the bottom caulked and re-sheathed with yellow metal
on keel.

Present Condition of the

Decks <u>Good</u>	Treenails <u>Good where seen</u>	Windlass and Capstan <u>Good</u>
Waterways <u>3</u>	Breasthooks and Stemson <u>3</u>	Pumps _____
Comings <u>3</u>	Transoms, Pointers, and Crutches _____	Boats <u>And</u>
Upper Deck Beams & Fastenings <u>3</u>	Timbers of the Frame _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings <u>3</u>	Keelsons _____	Sails <u>Sufficient</u>
Planksheers <u>3</u>	Clamps and Shelves _____	Anchors No. of _____
Sheerstrakes <u>3</u>	Ceiling _____	Cables <u>Where</u>
Topsides <u>3</u>	Rudder <u>Good</u>	Hawsers and Warps _____
Wales <u>3</u>	Copper <u>on keel</u> When put on <u>how</u>	Standing & Running Rigging <u>Good</u>
Plank (Bottom) and Counter _____		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where tried

This ship is in good and efficient condition,
eligible to remain as classed 14 A1

The Amount of Fee.....£ _____ is received by me,

Special..... 1 : 1 : _____

Certificate (if required) _____

Committee's Minute 13th August 1861

Character assigned 14 A1



© 2021

Lloyd's Register
Foundation

LON644-0350