

24129

REPORT of SURVEY for REPAIRS.

Rev 29/8/61

No. ⁸¹⁵ Survey held at London Date Aug 22nd 18 61
on the Ship "Mermaid" Master Merre
Tonnage 1321 Built at St Johns When built 1853
By whom built _____ Owners Messrs Wilson &
Port belonging to Liverpool Destined Voyage New Zealand
If Surveyed Afloat or in Dry Dock East India Dock

Last Survey, No. 24052 Port London Classed Cont-60-194-1

REPAIRS

Now done, the Main Mast renewed with Oregon Pine, the Fore Mast renewed with Iron. Composed of 3/8 bolts properly shifted, and strengthened by longitudinal angle Irons 4x3x1/2 four in number -

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Yellow Butul	Standing & Running Rigging
Plank (Bottom) and Counter	Copper on Felt When put on <u>1861</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

Made a careful survey of the Masts and Spars in obedience with the Committee's Orders of the 23rd Ultima and Con deemed the Fore and Main lower Masts - found the remaining spars in good condition - She is well in good and efficient Condition, fit in my opinion to remain as classed A. 1.

The Amount of Fee.....£..... is received by me,

Special.....2 : 2 : -

Certificate (if required) : 5 : -

Committee's Minute 30th August 18 61.

Character assigned Cont 20



© 2021

Lloyd's Register
Foundation

LON644-0377