

REPORT of SURVEY for REPAIRS.

No. 457 on the 13th "Sir Charles Forbes" Master
 Survey held at London Date Oct 14th 1861
 Tonnage 364 Built at Aberdeen When built 1824
 By whom built Owners J Holman
 Port belonging to Torsham Destined Voyage
 If Surveyed Afloat or in Dry Dock Afloat & Pontoon Victoria Dock

Last Survey, No. 23522 Port London Classed -A- in Red
 Rest to 50 2 10. 60
 S. 860. 5 grs.

REPAIRS

Found this vessel going on the Pontoon and was informed that she had been on shore and was very leaky; the vessel having been lifted, the starboard bilge appeared to be forced up, but the hold not being cleared could not ascertain the extent of injury inside; was informed by young Mr Holman that the owner of the vessel, his eldest brother, being dangerously ill, they only intended to stop the leaks and lay her by until the termination of his illness and that should he not recover she would be sold. Mr Holman sent has requested that her character may not be disturbed and I have referred him to the committee. The vessel has now been taken off the Pontoon and is laid up.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchor No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

Having stated all particulars above I beg respectfully to leave the matter in the hands of the Committee

The Amount of Fee.....£ is received by me, Thos. W. Brown

Special..... : :

Certificate (if required) : :

Committee's Minute 5th November 1861

Character assigned Expense Character

Notice to Owners
 Letter 5/11/61



© 2019

Lloyd's Register
 Foundation

LONG45-0003