

24479

# REPORT of SURVEY for REPAIRS.

No. <sup>832</sup> Survey held at London Date 15<sup>th</sup> & 18<sup>th</sup> Feb 1862  
on the Ship Surrey Master Lash  
Tonnage 1189 Built at Shields When built 1837  
By whom built \_\_\_\_\_ Owners Marshall  
Port belonging to London Destined Voyage for Melbourne  
If Surveyed Afloat or in Dry Dock Tindalls dry dock

Recd 20/2/62

Last Survey, No. 23978 Port London Classed 13A1  
4 61

## REPAIRS

The Yellow Metal Sheathing stripped off the bottom the ship caulked from keel to Waterways and the bottom resheathed with G.M. on paper

## Present Condition of the

Decks	<u>Good</u>	Treenails	<u>Good where seen</u>	Windlass and Capstan	<u>Good</u>
Waterways	✓	Breasthooks and Stemson	✓	Pumps	✓
Comings	✓	Transoms, Pointers, and Crutches	✓	Boats	<u>And</u>
Upper Deck Beams & Fastenings	✓	Timbers of the Frame	✓	Masts, Yards, &c.	✓
Lower Deck Beams & Fastenings	✓	Keelsons	✓	Sails	<u>Sufficient</u>
Planksheers	✓	Clamps and Shelves	✓	Anchors No. of	✓
Sheerstrakes	✓	Ceiling	✓	Cables	<u>Where</u>
Topsides	✓	Rudder	✓	Hawsers and Warps	✓
Wales	✓	Copper <u>G.M.</u> When put on <u>how done</u>		Standing & Running Rigging	<u>Seen</u>
Plank (Bottom) and Counter	✓				

## General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where tried

This ship is in good and efficient condition eligible to remain as classed 13A1

The Amount of Fee.....£..... is received by me,

Special..... / : / : .....

Certificate (if required) .....

Committee's Minute 26<sup>th</sup> February 1862

Character assigned 13A1  
recd 4/3



© 2019

Lloyd's Register Foundation