

24643

REPORT of SURVEY for REPAIRS.

Recd 22/4/62

No. 454 Survey held at London Date April 14th 1862
on the S. John Scott Master Harrison
Tonnage 655 Built at Sunderland When built 1857
By whom built _____ Owners J. Lidgett
Port belonging to London Destined Voyage _____
If Surveyed Afloat or in Dry Dock Timberln dry dock

Last Survey, No. 23104 Port London Classed 13 A 1
60

REPAIRS

Yellow metal stripped off recaulked from keel to metal line and the yellow metal sheathing renewed on ^{part} Felt and part paper
Sixteen broken Ruder bolts renewed with yellow metal and about four hundred and fifty galvanized dump bolts driven in lower hold ceiling.

Present Condition of the

Decks	Good where seen	Treenails	Good where seen	Windlass and Capstan	Good and sufficient
Waterways		Breasthooks and Stenson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Keelsons		Sails	
Planksheers		Clamps and Shells		Anchors No. of	
Sheerstrakes		Ceiling		Cables	
Topsides		Rudder		Hawsers and Warps	
Wales		Copper <u>on T</u> When put on <u>now</u>		Standing & Running Rigging	
Plank (Bottom) and Counter					

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. good where tested

This vessel is now in a good and efficient state of repair and is eligible in my opinion to remain classed

The Amount of Fee.....£..... is received by me,

Special..... 1: 1: 1

Certificate (if required) : :

Thos. W. Wain

Committee's Minute 9th May 1862
Character assigned 13 A 1
WA record 4/11



© 2019

Lloyd's Register Foundation

LON645-0360