

24700

REPORT of SURVEY for REPAIRS.

No. 170 Survey held at London Date 16th Apr^l to 14th May 1862
on the S. "Result" MasterTonnage 1465 Built at Boston When built 1853By whom built _____ Owners R Green &Port belonging to London Destined Voyage AustraliaIf Surveyed Afloat or in Dry Dock Mr^s Green's dry dock & E S DockLast Survey, No. 23916 Port London Classed 7 A 1
REPAIRS Cont^{to} - 2 yrs

Green Metal in good order and not wrinkled, one short piece of Topside planking port side in way of fore channels renewed with Pitch Pine, timbers there exposed good, caulked above metal line where required, upper deck & Waterways recaulked and the deck double with 2 in dantzig pine on felt fastened with galvanised iron bolts -

Present Condition of the

| | | |
|---|--|----------------------------|
| Decks <u>Upper double on felt 1862</u> | Treenails | Windlass and Capstan |
| Waterways <u>recaulked</u> | Breasthooks and Stemson | Pumps |
| Comings | Transoms, Pointers, and Crutches | Boats |
| Upper Deck Beams & Fastenings | Timbers of the Frame | Masts, Yards, &c. |
| Lower Deck Beams & Fastenings | Keelsons | Sails |
| Planksheers | Clamps and Shelves | Anchors No. of |
| Sheerstrakes | Ceiling | Cables |
| Topsides | Rudder | Hawsers and Warps |
| Wales | Copper <u>RTYH</u> When put on <u>1861</u> | Standing & Running Rigging |
| Plank (Bottom) and Counter <u>ft 2 1858</u> | | |

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

Good where tested
This ship appears where seen in good condition and in our opinion eligible to continue as Classed A 1

Will^m B. Davey

The Amount of Fee.....£..... is received by me,

Special Atten.
dancer

Certificate (if required)

Committee's Minute 3rd June 1862.Character assigned Cont 2 A 1

© 2019

Lloyd's Register
Foundation

LONG45-0414