

24759

REPORT of SURVEY for REPAIRS.

No. 22 Survey held at London Date 2nd June to 3rd July 1862
on the B. J. Talbot Master Pratt
Tonnage 250 Built at Southampton When built 1851
By whom built _____ Owners Newman & Hunt
Port belonging to London Destined Voyage _____
If Surveyed Afloat or in Dry Dock Fountain dry dock

Rev. 4.7.62

Last Survey, No. 23048 Port London Classed 1541
2-60

REPAIRS

The following has now been renewed with English Oak from decay

On the Starboard side twenty frames in the fore Cant Body excepting 7 short Lofttimbers, two shifts of outside planking. On the Port side, nineteen frames in the fore Cant Body excepting 10 short Lofttimbers, one second futtock, all the Ceiling Clamps &c in way of the defective timbers from the Deck Shelf down to the Keelson, foremast piece of Keelson renewed

Treenails in the Sides and After frame have been driven out for examination in the Sides they were found to be generally good but several in the After Cant frame and the timbers through which they pass were seriously defective

Sent notice Card to the Owners requesting a further

Present Condition of the

Decks	Treenails <u>part renewed part defective</u>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame <u>defective part</u>	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves <u>renewed</u>	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

I am of opinion this vessel's character should be repaired until the above requisitions have been complied with, and the ship is put into an efficient state of repair

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

E. M. Bouchman

Committee's Minute 4th July 1862

Character Assigned

Expense Character

Notice to owner

Dr 4/7/62



© 2019

Lloyd's Register Foundation

LON 645-0472

24759. Sam.

examination to be made with a view to its removal
which they have declined to do and have since com-
menced to close up the ship

J.R. Buchanan



© 2019

Lloyd's Register
Foundation