

24774

REPORT of SURVEY for REPAIRS.

Rev 1/7/62

No. 343 on the S. "Hudson Castle" Survey held at London Master Pice Date 26th May to June 1862

Tonnage 1074 Built at Sunderland When built 1857

By whom built C Owners R. Green

Port belonging to London Destined Voyage Bombay

If Surveyed Afloat or in Dry Dock Mr Green's dry dock East India dock

Last Survey, No. 23960 Port London Classed 13A1

REPAIRS

Yellow Metal stripped off, recaulked from keel to gunwale also decks and waterways and the bottom sheathed with Yellow Metal a paper new main mast partners to upper deck & one short plank of deck between after hatchway and main mast

Present Condition of the

Decks		Treenails		Windlass and Capstan	<u>Good</u>
Waterways		Breasthooks and Stemson		Pumps	<u>do</u>
Comings	<u>Good</u>	Transoms, Pointers, and Crutches	<u>Good</u>	Boats <u>6 No</u>	<u>do</u>
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	<u>do</u>
Lower Deck Beams & Fastenings	<u>where</u>	Keelsons	<u>where</u>	Sails	<u>do</u>
Planksheers		Clamps and Shelves		Anchors No. of <u>3/3. 15 & 16</u>	
Sheerstrakes		Ceiling	<u>seen</u>	Cables	<u>Complete</u>
Topsides		Rudder		Hawsers and Warps	<u>do</u>
Wales	<u>seen</u>	Copper <u>Y Mon</u> When put on <u>1862</u>		Standing & Running Rigging	<u>do</u>
Plank (Bottom) and Counter					

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

Good where tested
This ship is at present where seen in good condition and eligible to continue as classed A1

The Amount of Fee.....£..... is received by me,

Special Caulk 1 : 1 : -

Certificate (if required) : 5 : -

Committee's Minute 15th July 1862.

Character assigned 13A1

Wm L. Davey

J. A. Martin



© 2019

Lloyd's Register Foundation

LON645-0487

Windsor Castle

Does to complete
see hole inside



© 2019

Lloyd's Register
Foundation