

REPORT of SURVEY for REPAIRS.

No. 634 Survey held at London Date 16th June 18 62
on the M^{rs} Mary Russell Mitford Master Deason
Tonnage 529 Built at Shields When built 1855
By whom built _____ Owners Walker & Co
Port belonging to Scarboro Destined Voyage Cardiff & Mauritius
If Surveyed Afloat or in Dry Dock New Crane dry dock

Last Survey, No. 15029 Port Liverpool Classed SA1
50

REPAIRS

The Boot-topping has now been stripped off and the seam in the way of the same recaulked
Brow-sprit and Fore Mast new

Present Condition of the

Decks <u>Good</u>	Treenails <u>good where seen</u>	Windlass and Capstan <u>2 Dr Good Suffs</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>2</u> <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>3</u> <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>"</u>	Sails <u>DS</u> <u>"</u>
Planksheers <u>Good where seen</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>3 B. 1 S. 1 1/2</u> <u>"</u>
Sheerstrakes <u>"</u>	Ceiling <u>1</u>	Cables <u>"</u>
Topsides <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	<u>2 Dr</u> <u>Copper on felt</u> When put on <u>1861</u>	Standing & Running Rigging <u>4</u>
Plank (Bottom) and Counter <u>"</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where tried

condition This vessel is in good and efficient
condition eligible to remain as Classed SA1

The Amount of Fee.....£ _____ is received by me,

Special..... : : _____

Certificate (if required) : : _____

Committee's Minute 18th July 18 62

Character assigned SA1 _____



© 2019

Lloyd's Register
Foundation

LON645-0492