

24875

REPORT of SURVEY for REPAIRS.

No. 352 on the 43 1/2 Dunmore Survey held at London Date 26th July 1862
Master P. Doward
Tonnage 439 Built at Alloa When built 1861
By whom built _____ Owners J. Adamson
Port belonging to Glasgow Destined Voyage _____
If Surveyed Afloat or in Dry Dock Nelson dry dock

Last Survey, No. 2986 Port Leith Classed 10 A 1
61

REPAIRS

Recalked from keel to metal line and re-shathed with yellow metal on

Present Condition of the

Decks	<i>Good where seen</i>	Treenails	<i>Good where seen</i>	Windlass and Capstan	<i>Good & sufficient</i>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Keelsons		Sails	
Planksheers		Clamps and Shelves		Anchors No. of	
Sheerstrakes		Ceiling		Cables	
Topsides		Rudder		Hawsers and Warps	
Wales		Copper <u>YMC</u> When put on <u>now</u>		Standing & Running Rigging	
Plank (Bottom) and Counter					

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

good where tested
This vessel is now in a good and efficient state and is eligible in our opinion to remain as classed 10 A 1

The Amount of Fee.....£ : : is received by me, 10 A 1

Special charge 3: 3: — } Thos H. Wain
Certificate (if required) : 5: — }

Committee's Minute 5 September 1862

Character assigned 10 A 1

No repair

Received