

24882

# REPORT of SURVEY for REPAIRS.

No. 280 Survey held at London Date August 26<sup>th</sup> 18 62  
on the Brig "Fortitude" Master James Collins  
Tonnage 191 Built at Lochin When built 1845  
By whom built                      Owners Hilbery  
Port belonging to London Destined Voyage Lagos  
If Surveyed Afloat or in Dry Dock in globe dock

Recd 4.9.62

Last Survey, No. 17302 Port Liverpool Classed 9 A1 m red  
SS. 58. 6 yrs C.S. 12. 61

## REPAIRS

Done at this date. Repaired metal and tested caulking, and caulked from yellow metal to gunwale

Present Condition of the			
Decks	<u>Good</u>	Treenails	<u>when seen Good</u>
Waterways	"	Breasthooks and Stenson	"
Comings	"	Transoms, Pointers, and Crutches	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame	<u>when seen</u>
Lower Deck Beams & Fastenings	"	Keelsons	"
Planksheers	"	Clamps and Shelves	"
Sheerstrakes	"	Ceiling	"
Topsides	"	Rudder	"
Wales	"	Copper <u>YM</u>	When put on <u>1858</u>
Plank (Bottom) and Counter	"		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good

Is now in good and efficient condition fit to carry dry and perishable cargoes to and from all parts of the world and is entitled to continue as classed

The Amount of Fee.....£..... is received by me,

Special..... 1 : 1 : 0

Certificate (if required) .....

Committee's Minute 9<sup>th</sup> September 18 62

Character assigned As per



© 2019  
Lloyd's Register  
Foundation  
LON 646-0073