

REPORT of SURVEY for REPAIRS.

No. 430 Survey held at London Date Aug 6th to Sep 2nd 1862
on the Ship "Hornet" Master Pryme
Tonnage 1156 Built at St. Johns When built 1853
By whom built Owners G. Marshall
Port belonging to London Destined Voyage Bombay
If Surveyed Afloat or in Dry Dock Union Dry Dock & East India Dock -
Last Survey, No. 23833 Port London Classed Cont. to - 2A.1.
S.S. 61 - 5 Frs 61

REPAIRS

Now done, a short piece of Gripe renewed and a piece let into the side of the Keel forward, where chafed by the Chain - the Caulking of the bottom tested and found good - the Yellow Metal sheathing patched.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Budder	Hawsers and Warps
Wales	Yellow Metal	Standing & Running Rigging
Plank (Bottom) and Counter	When put on 1861	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where seen -

She is in good Condition, fit for the safe conveyance of dry and perishable cargoes to and from all parts of the world and to remain classed A.1.

The Amount of Fee.....£..... is received by me, Edward Bouchman

Special..... : : :

Certificate (if required) : : :

Committee's Minute 9th September 1862

Character assigned Cont. 2A.1



© 2019

Lloyd's Register Foundation

LON 646-0078