

24893

REPORT of SURVEY for REPAIRS.

change of owners -

No. 336 Survey held at London Date September 11th 1862
on the Y^h "Porcia" Master Cosens

Tonnage 704 ~~604~~ Built at Sunderland When built 1844

By whom built _____ Owners Gellatly &

Port belonging to London Destined Voyage India

If Surveyed Afloat or in Dry Dock Witley cross dry dock & East India Dock

Last Survey, No. 23575 Port London Classed 9 A 1 in Red
REPAIRS SS. 56 - logs caps omitted

The yellow metal sheathing stripped off, the ship re-caulked from keel to metal line and the yellow metal sheathing renewed on Felt

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>1st Y.M.</u> When put on <u>1862</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where tested

"This vessel is now in a good and efficient state of repair fit for the conveyance of dry and perishable cargoes to and from all parts of the world" and is eligible in our opinion to be reentered

The Amount of Fee.....£ 1 : - : - is received by me,

Special..... 1 : 1 : -

Certificate (if required) : 5 : -

Committee's Minute 15th September 1862

Character assigned 1 in Red



© 2019

Lloyd's Register Foundation

LON666-0085