

24924

Recd 25/9/62

REPORT of SURVEY for REPAIRS.

No. 14 Survey held at London Date August 9th 1862
on the S. "Saladin" Master J. H. Baillie
Tonnage 856 Built at Sunderland When built 1857
By whom built _____ Owners Henderson
Port belonging to London Destined Voyage Calcutta
If Surveyed Afloat or in Dry Dock Princes dry dock
Last Survey, No. 23774 Port London Classed 13A1

REPAIRS

Yellow metal repaired - Recaulked from metal line to middle line of deck -

Present Condition of the

Decks	<i>Good where seen</i>	Treenails	<i>Good where seen</i>	Windlass and Capstan	<i>Good & sufficient</i>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Keelsons		Sails	
Planksheers		Clamps and Shells		Anchors No. of	
Sheerstrakes		Ceiling		Cables	
Topsides		Rudder		Hawsers and Warps	
Wales		Copper <u>1 1/2</u> When put on <u>1860</u>		Standing & Running Rigging	
Plank (Bottom) and Counter					

General Observations and Opinion, _____ Caulking of Bottom, Deck, & Waterways. good where tested

This vessel is now in good and efficient condition and is eligible in my opinion to remain classed

The Amount of Fee.....£ _____ is received by me
Special..... 1: 1: -
Certificate (if required) : 5: -

Committee's Minute 26 September 1862
Character assigned 13A1