

24950

Damage &c
REPORT of SURVEY for REPAIRS.

No. 530 Survey held at London Date August to Sept. 10th 1862
on the Ship "Ellenborough" Master Thos H. Withers
Tonnage 926 Built at Newcastle When built 1842
By whom built _____ Owners G. Marshall
Port belonging to London Destined Voyage Calcutta
If Surveyed Afloat or in Dry Dock Ship's Youngs' Dry Dock -

Rest. S. 10/62

Last Survey, No. 24021 Port London Classed Rest. S. 10/62

REPAIRS *Now done, the whole of the yellow metal sheathing stripped off the bottom, the ship hung in shores and Caulked from the keel to the gunwale, eighteen feet of false keel forward renewed, and she has been supplied with a Bower Anchor of about 40 Cwt. and with 65 Fathom of 1 1/2" Chain Cable -*

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways <i>Good</i>	Breasthooks and Stems	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings <i>Good</i>	Keelsons <i>Good where seen</i>	Sails <i>Good and suff.</i>
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides <i>Caulked</i>	Rudder <i>Yellow Metal</i>	Hawsers and Warps
Wales	<i>Copper on left</i> When put on <i>now</i>	Standing & Running Rigging
Plank (Bottom) and Counter <i>Caulked</i>		

General Observations and Opinion, *Caulking of Bottom, Deck, & Waterways. Good where tested.*
She is now in good and efficient Condition, fit in my opinion to remain as classed S. 1.
W. Maymouth

The Amount of Fee.....£ _____ is received by me,
Special..... *1/3 : 1/3 : -*
Certificate (if required) _____

Committee's Minute 10th October 1862.
Character assigned Rest S. 1 record
Damage fee £ 3..3..0
Charge for extra attendance 1..1..0