

24951

Nov. 13. 8. 62

REPORT of SURVEY for REPAIRS.

No. 98 Survey held at London Date July 17th 18 62
In the Ship "Suffolk" Master Martin
Tonnage 976 Built at Northam When built 1837
By whom built _____ Owners Ships^r Wigram & Co
Port belonging to London Destined Voyage Australia
If Surveyed Afloat or in Dry Dock Ships^r Wigram's Dry Dock

Last Survey, No. 24249 Port London Classed 13A.1.
10.61

REPAIRS

Now done, Caulked throughout, including the decks - and her bottom sheathed with Yellow Metal on Telt

Present Condition of the

| | | |
|-------------------------------|--|----------------------------|
| Decks | Treenails | Windlass and Capstan |
| Waterways | Breasthooks and Stemson | Pumps |
| Comings | Transoms, Pointers, and Crutches | Boats |
| Upper Deck Beams & Fastenings | Timbers of the Frame | Masts, Yards, &c. |
| Lower Deck Beams & Fastenings | Keelsons | Sails |
| Planksheers | Clamps and Shelves | Anchors No. of |
| Sheerstrakes | Ceiling | Cables |
| Topsides | Buddles | Hawsers and Warps |
| Wales | <u>Yellow Metal</u> | Standing & Running Rigging |
| Plank (Bottom) and Counter | <u>Copper on Telt</u> When put on <u>now</u> | |

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

Good where tested - She is now in good and efficient Condition, fit in my opinion to remain as classed 13A.1.

B. Wymouth

The Amount of Fee.....£..... is received by me,

Special..... 1 : 1 : *RL*

Certificate (if required) : :

Committee's Minute 17th October 18 62

Character assigned 13A.1 - record

Charge £ 1. 1. 0



© 2019
Lloyd's Register
Foundation
LON 646-0150