

24963

REPORT of SURVEY for REPAIRS.

No. 887 on the BK "Excelsior" Survey held at London Date Oct 2nd 8th 18 62
Master A. H. Bond
Tonnage 494 Built at Littlehampton When built 1856
By whom built ✓ Owners Langley
Port belonging to Portsmouth Destined Voyage Colombo, Ceylon
If Surveyed Afloat or in Dry Dock in New frame dock

11/25/13 10/10/12

Last Survey, No. 24393 Port London Classed 13 A1
9.60

REPAIRS

Stripped Yellow metal sheathing caulked from keel to upper part of
Wales and re-sheathed with Yellow metal over paper.

Present Condition of the

Decks	<u>Good</u>	Treenails	<u>Good</u>	Windlass and ^{Winch} Capstan	<u>Good</u>
Waterways	"	Breasthooks and Stemson	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame	<u>where seen</u>	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Keelsons	"	Sails	"
Planksheers	"	Clamps and Shelves	"	Anchors	No. of <u>3-B, 1-S, 1-K</u>
Sheerstrakes	"	Ceiling	"	Cables	"
Topsides	"	Rudder	"	Hawsers and Warps	"
Wales	"	Copper <u>YM</u>	When put on <u>1862</u>	Standing & Running Rigging	"
Plank (Bottom) and Counter	"				

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where tested

Is now in good and efficient condition and in our opinion fit to
remain as classed

The Amount of Fee.....£..... is received by me,

Special..... 1 : 1 : 0

Certificate (if required) : 5 :

Committee's Minute 17th October 1862.

Character assigned 13 A1



© 2019

Lloyd's Register
Foundation

LON 646-0152

Excelsior



© 2019

Lloyd's Register
Foundation