

REPORT of SURVEY for REPAIRS.

24958

Rev 1/19/62

No. 109 Survey held at London Date August 4th 18 62
on the S. "Capiolani" Master Shield
Tonnage 533 Built at Sunderland When built 1859
By whom built _____ Owners J. Patton
Port belonging to Shields Destined Voyage _____
If Surveyed Afloat or in Dry Dock Bullhead dry dock

Last Survey, No. 23939 Port London Classed 10 A 1
5.61

REPAIRS

*Yellow metal stripped caulked from keel to plank sheers
and the yellow metal sheathing renewed on Felt*

Present Condition of the

Decks	<i>Good where seen</i>	Treenails	<i>Good where seen</i>	Windlass and Capstan	<i>In good order & sufficient</i>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Keelsons		Sails	
Plank sheers		Clamps and Shelves		Anchors No. of	
Sheerstrakes		Ceiling		Cables	
Topsides		Rudder		Hawsers and Warps	
Wales		Copper <u>T & Y M</u> When put on <u>now</u>		Standing & Running Rigging	
Plank (Bottom) and Counter					

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where tested

*This vessel is now in good condition and is
eligible in my opinion to remain classed*

The Amount of Fee.....£..... is received by me,

Special..... 1: 1: *Re*

Certificate (if required).....

Committee's Minute 21st October 18 62

Character assigned 10 A 1

Swankie & Co. Brokers Fenchurch St



© 2019

Lloyd's Register
Foundation

LON 646-0157