

24988

REPORT of SURVEY for REPAIRS.

Recd 20/10/62
C.H.

No.

454
on the

Survey held at

London

Date

Oct 6th

1862

S. Chowringhee

Master

Dixon

Tonnage

781

Built at

Sunderland

When built

1857

By whom built

Owners

A. G. Robinson

Port belonging to

London

Destined Voyage

If Surveyed Afloat or in Dry Dock

in Nelson dock

Last Survey, No.

23768

Port

London

Classed

13 A1
3.61

REPAIRS

Stripped yellow metal; renewed a length of upper deck clamp; introduced 6 pairs of hanging knees to lower deck; put on a false keel of English elm; caulked from keel to Planksheer and re-sheathed with yellow metal over felt

Present Condition of the

Decks

Good

Waterways

"

Comings

"

Upper Deck Beams & Fastenings

"

Lower Deck Beams & Fastenings

"

Planksheers

"

Sheerstrakes

"

Topsides

"

Wales

"

Plank (Bottom) and Counter

"

Treenails

where seen

Good

Breasthooks and Stenson

"

Transoms, Pointers, and Crutches

"

Timbers of the Frame

where seen

"

Keelsons

"

Clamps and Shelves

"

Ceiling

"

Rudder

"

Copper

F.Y.M.

When put on

1862

Windlass and Capstan

Good

Pumps

"

Boats

"

Masts, Yards, &c.

"

Sails

"

Anchors No. of 1 B, 1 S, 1 K

Cables

"

Hawsers and Warps

"

Standing & Running Rigging

"

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

Good where tested

Is now in good and efficient condition and is in our opinion fit to remain as classed

The Amount of Fee.....£ 1 : — : —

Special..... 1 : 1 : 0

Certificate (if required) : : :

is received by me,

John Maxwell

Thos. W. Wawn

Committee's Minute

24th October

1862

Character assigned

13 A1

record 4M



© 2019

Lloyd's Register
Foundation

LON 646-0177