

24989

REPORT of SURVEY for REPAIRS.

S.P. for A1 in Red 1st rule.

No. 650 on the B.E. "Emperor" Survey held at London Date Sept 2^d 10th 18 62
 Master A. Pigeon
 Tonnage 264 200 Built at Aberdeen When built 1849
 By whom built Owners A. Hunter
 Port belonging to London Destined Voyage Coasting
 If Surveyed Afloat or in Dry Dock In Princes Dock

Nov 10/62

Last Survey, No. 24198 Port London Classed 9 omitted
C.3 9.61

REPAIRS

Scraped bright from light mark upwards, drove out bolts and treenails as per Rule Section 60.

Renewed one length of Rider Keelson of American Oak; one length of Upper deck clamp of Cantyic Oak; two lengths of ceiling of Cantyic Oak; scarphed one Beam arm with Greenheart; caulked from light mark to upper part of Wales with all butts of bottom, keel seam & hood ends.

Present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and ^{Winch} Capstan <u>Good</u>
Waterways <u>"</u>	Breasthooks and Stenson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>good where seen</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>"</u>	Sails <u>"</u>
Planksheers <u>"</u>	Clamps and Shelves <u>pt new good</u>	Anchors No. of <u>3B, 1S 1K</u>
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables <u>"</u>
Topsides <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Copper <u>When put on</u>	Standing & Running Rigging <u>"</u>
Plank (Bottom) and Counter <u>"</u>		

General Observations and Opinion,**Caulking of Bottom, Deck, & Waterways.**

Surveyed in strict accordance with the Rule Sec. 60 first part
 Is now in good and efficient condition fit for the safe conveyance of dry and perishable cargoes to and from all parts of the world and is in our opinion fit to be classed A1 in Red from the present time.

The Amount of Fee.....£ 3 :

is received by me,

Special.....£ 3 :

Certificate (if required).....

Committee's Minute

24th October 18 62.

Character assigned

A1 in Redrecord repair

© 2019

Lloyd's Register
Foundation

LON 646-0178