

REPORT of SURVEY for REPAIRS.

change of owner.

No. 194 on the Y^h "Reullura" Survey held at London Date Novr 17th 18 62
Master J Patterson
Gross Tonnage 288 $\frac{1}{2}$ Built at Sunderland When built 1858
By whom built _____ Owners Manning & Anderson
Port belonging to London Destined Voyage West Indies
If Surveyed Afloat or in Dry Dock Globe dry dock & London Dock

Last Survey, No. 24439 Port London Classed GA 1
1, 62

REPAIRS

*Four piece of keelson renewed with Teak and stemson
knee with English Oak*

Present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Keelsons		Sails	
Planksheers		Clamps and Shelves		Anchors No. of	
Sheerstrakes		Ceiling		Cables	
Topsides		Rudder		Hawsers and Warps	
Wales		Copper <u>1' 4" x 1/2"</u> When put on <u>1861</u>		Standing & Running Rigging	
Plank (Bottom) and Counter					

Good where seen

Good where seen

Good and sufficient

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. good where tested

*This vessel is now in good condition and is
eligible in our opinion to remain classed*

The Amount of Fee.....£ 1 : — : — is received by me, Thos W. Wawn
Special..... 2 : 2 : —
Certificate (if required) : 5 : —

Committee's Minute 20th January 18 63

Character assigned GA 1
second repair

