

25151

# REPORT of SURVEY for REPAIRS.

No. 296 Survey held at London Date Jan 7<sup>th</sup> 18 63  
on the S. "Dovercourt" Master Isaac Heigho  
Tonnage 531 Built at Harwich When built 1861  
By whom built Vaux Owners S. W. Madams  
Port belonging to London Destined Voyage Bombay  
If Surveyed Afloat or in Dry Dock in Ratcliff Dock

Last Survey, No. 1075 Port Swanwich Classed 10A1  
61

REPAIRS for damage see Special report.

Stripped Yellow metal sheathing caulked from keel to metal line and re-sheathed with Yellow metal over felt.

Present Condition of the			
Decks	<u>Good</u>	Treenails	<u>where seen Good</u>
Waterways	"	Breasthooks and Stemson	"
Comings	"	Transoms, Pointers, and Crutches	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame	"
Lower Deck Beams & Fastenings	"	Keelsons	"
Planksheers	"	Clamps and Shelves	"
Sheerstrakes	"	Ceiling	"
Topsides	"	Rudder	"
Wales	"	Copper <u>F &amp; Y M</u> When put on <u>1863</u>	
Plank (Bottom) and Counter	"	Windlass and Capstan	<u>Good</u>
		Pumps	"
		Boats	"
		Masts, Yards, &c.	"
		Sails	"
		Anchors	No. of <u>3B, 1S, 1K</u>
		Cables	"
		Hawsers and Warps	"
		Standing & Running Rigging	"

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. where tested Good

Is now in good and efficient condition and is in my opinion fit to remain as classed

The Amount of Fee.....£ 2 : 2 : 0 is received by me,  
Special.....1 : 1 : 0

John Maxwell

Certificate (if required) .....

Committee's Minute 23rd January 18 63

Character assigned 1075 record



Document



© 2019

Lloyd's Register  
Foundation