

25358

## REPORT of SURVEY for REPAIRS.

No. 339

on the

Survey held at LondonDate Mar 12<sup>th</sup> 1863Ship "Sea Star"

Master

LouittTonnage 634

Built at

Aberdeen

When built

1833

By whom built

Owners

Livingstone

Port belonging to

Glasgow

Destined Voyage

Australia

If Surveyed Afloat or in Dry Dock

Dept<sup>o</sup> Green's Dry Dock

Last Survey, No.

24641

Port

London

Classed

G.A. 1.

## REPAIRS

Now done, her bottom Caulked and sheathed with Yellow Metal on Telt. - A short piece of Stag Keelson abaft under the Duzen Mast renewed with Teak, and the main Keelson under it - trimmed down.

## Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams &amp; Fastenings

Lower Deck Beams &amp; Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Treenails

Breasthooks and Stimson

Transoms, Pointers and Crutches

Timbers of the Frame

Keelsons

Clamps and Shelves

Ceiling

Radder

Yellow Metal on Telt - When put on

how

Windlass and Capstan

Pumps

Boats

Masts, Yards, &amp;c.

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing &amp; Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, &amp; Waterways.

is now in good and efficient condition, fit in my opinion to remain as classed G.A. 1.

The Amount of Fee.....£

is received by me,

Special..... 2 : 2 :

Certificate (if required) : :

Committee's Minute

21<sup>st</sup> April

18

63.

Character assigned

G.A. 1 - record 4MCharge £1.2.0

© 2021

Lloyd's Register Foundation

LON667-0064