

25366

REPORT of SURVEY for REPAIRS.

No. 837 Survey held at Gt Yarmouth Date April 11th 18 63
 on the Yⁿ "Arab" Master Jas Bloom
 Tonnage 189 Built at Yarmouth When built 1841
 By whom built _____ Owners Betts & Co
 Port belonging to Yarmouth Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Hellows' dry dock & afloat

Last Survey, No. 1243 Port Yarmouth Classed 12 A 1
 Rest 58 — 8 58

REPAIRS

The windlafs renewed with English Oak, Rudder braces refastened — Recaulked from keel to plank sheers and the yellow metal sheathing renewed —

Present Condition of the

Decks		Treenails		Windlass and Capstan ^{new} <u>Much good</u>
Waterways		Breasthooks and Stemson		Pumps <u>2 of Iron</u> "
Comings		Transoms, Pointers, and Crutches		Boats <u>two</u> "
Upper Deck Beams & Fastenings <u>Good</u>		Timbers of the Frame <u>Good</u>		Masts, Yards, &c. <u>sufficient</u> "
Lower Deck Beams & Fastenings <u>where</u>		Keelsons <u>where</u>		Sails <u>sufficient</u> "
Plank sheers <u>seen</u>		Clamps and Shelves <u>seen</u>		Anchors No. of <u>2 B 1 S 2 K</u>
Sheerstrakes <u>seen</u>		Ceiling		Cables <u>180 fms</u>
Topsides		Rudder		Hawsers and Warps <u>8: 5 1/2 : 4 1/2</u>
Wales		Copper <u>SM</u> When put on <u>now</u>		Standing & Running Rigging <u>good</u>
Plank (Bottom) and Counter				

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where tested

This vessel is now in good condition and is eligible in my opinion to remain classed A 1

The Amount of Fee.....£ _____ is received by me, Thos M. Wain
 Special..... 1: 1: }
 Certificate (if required) : 2: 6 }

Committee's Minute 24th April 18 63
 Character assigned Rest 8 1/2

Expenses 2. 2.



© 2021

Lloyd's Register
Foundation

LON647-0072