

25383

REPORT of SURVEY for REPAIRS.

change of owners

No. ³⁵³ Survey held at London Date March 18 63
 on the S. Dunphaile Castle Master _____
 Tonnage 720 Built at Sunderland When built 1861
 By whom built Laing Owners J. Allan
 Port belonging to London Destined Voyage Madras
 If Surveyed Afloat or in Dry Dock Limetkiln dry dock

Last Survey, No. 7292 Port Sunderland Classed 13A1

10-41

REPAIRS

Now done: the yellow metal sheathing stripped, recaulked throughout and resheathed with yellow metal over felt.

Added,
 Eight pairs of diagonal iron riders extending from clamp to limberstrakes fastened with yellow metal also four wood and two iron spurs to poop and an iron crutch in the tween decks—

Present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	<u>Good</u>	Keelsons	<u>Good</u>	Sails	<u>Good</u>
Planksheers		Clamps and Shelves		Anchors No. of	
Sheerstrakes		Ceiling		Cables	
Topsides		Rudder		Hawsers and Warps	
Wales		Copper <u>T & J M</u> When put on <u>now</u>		Standing & Running Rigging	
Plank (Bottom) and Counter					

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where tested

This vessel is eligible in our opinion to remain
 classed 13A1

The Amount of Fee.....£ 1 : — : — is received by me,

Special..... 1 : 1 : —

Certificate (if required) _____

Committee's Minute 1st May 18 63Character assigned 13A1

Record J.M.

Thos. Wm. Mawson
 John Maxwell



© 2021

Lloyd's Register
 Foundation
 LON647-0087