

25655

REPORT of SURVEY for REPAIRS.

No.

31

on the

Survey held at

London

Date July 1st to 30th 1863

Ship

"Duncan Dunbar"

Master

J. Swans ^{son} ~~Swans~~

Tonnage

1374

Built at

Sunderland

When built

1837

By whom built

Owners

~~Swans~~ Gellatly & Co No change

Port belonging to

London

Destined Voyage

Sydney

If Surveyed Afloat or in Dry Dock

Canal Dry Dock & E. J. Dock

Last Survey, No.

24033

Port

London

Classed

13A 1/1

REPAIRS

Now done, Caulked from keel to Gunwale and
her bottom sheathed with yellow metal on felt.

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Bulldoz

Yellow metal on felt - When put on

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

She is now in good and efficient condition, fit
in my opinion to remain as classed 13A 1/1.

The Amount of Fee.....£..... is received by me;

Special.....2 : 2 : -

Certificate (if required) : :

Committee's Minute

1st September 1863

Character assigned

13A 1/1

received Gellatly



© 2021

Lloyd's Register
Foundation

LON 647-0325