

25720

REPORT of SURVEY for REPAIRS.

No. 364 Survey held at London Date Sep 11th 1863
on the Ship "Marshal Telissier" Master Porter
Tonnage 612 Built at Sunderland When built 1855
By whom built _____ Owners Messrs Blyth & Co
Port belonging to London Destined Voyage Mauritius
If Surveyed Afloat or in Dry Dock Young's Dry Dock

Last Survey, No. 25216 Port London Classed 10 A1
63

REPAIRS

Now done, Caulked from Keel to Gunwale and Bottom sheathed with Yellow Metal upon Felt

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastening	Ditto Ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	<u>4.9m</u> <u>Copper</u> on felt When put on <u>now</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where tested

She is now in good condition, and fit in our opinion for the safe conveyance of dry and perishable goods to and from all parts of the world and to remain

The Amount of Fee.....£..... is received by me,

Special..... 1: 1: -

Certificate (if required)

Committee's Minute 29 September 1863

Character assigned 10 A1

Charge £ 1.1. -

as classed 10 A1
Mornich
B. W. Raymond

