

25764

REPORT of SURVEY for REPAIRS.

25764

No. \_\_\_\_\_ Survey held at London Date Sep 1<sup>st</sup> 3<sup>rd</sup> 18 63  
on the Ship Haby Castle Master Leaman et. Sharp  
Tonnage 692 Built at Sunderland When built 1856  
By whom built \_\_\_\_\_ Owners Messrs Greenwell & Hall  
Port belonging to London Destined Voyage Calcutta.  
If Surveyed Afloat or in Dry Dock Young's Dry Dock  
Last Survey, No. 21878 Port London Classed 10 A 1  
62

REPAIRS

Now done, Bottom caulked and sheathed with Yellow Metal on Felt, the Butts of Topsides and Wales and the Seam under covering board caulked, 14 bolts of Upper and 5 of Lower Deck knees renewed with Yellow Metal - The ceiling extra fastened with 200 dunnops

280 Lbs 15 1/2 & 1 1/4 lb Also 3 Anchors  
Proved at Booming House  
Cost No. 2472170.

Present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways		Breasthooks and Stenson		Pumps	
Comings	good	Transoms, Pointers, and Crutches	good	Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	good
Lower Deck Beams & Fastenings	where	Ditto Ditto at other places	where	Sails	and
Planksheers	seen caulked	Keelsons		Anchors No. of	
Sheerstrakes	butts caulked	Clamps and Shelves	Seen	Cables	efficient
Topsides	butts caulked	Ceiling	extra fastened with 200 dunnops	Hawsers and Warps	
Wales	butts caulked	Rudder	Y.M. on Felt	Standing & Running Rigging	
Plank (Bottom) and Counter	caulked	Copper	When put on		now

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where tested

She is now in our opinion fit for the conveyance of dry and perishable goods to and from all parts of the world and to remain as

Classed 10 A 1

The Amount of Fee.....£..... is received by me,

Special..... 1 : 1 : R. Fleet

Certificate (if required) : 5 : R. Waymouth

Committee's Minute 27<sup>th</sup> October 1863

Character assigned 10 A 1

Charge £ 1-1

received W. G. A.



© 2021

Lloyd's Register Foundation  
CON647-0431