

25834

REPORT of SURVEY for REPAIRS.

No. 272 Survey held at London Date Nov 10th 1863
on the Ship "Scotland" Master Campbell
Tonnage 1170 Built at Quebec When built 1861
By whom built _____ Owners J. & A. Watt
Port belonging to Glasgow Destined Voyage _____
If Surveyed Afloat or in Dry Dock Union Dry Dock

Rev. 24. 11. 63

Last Survey, No. 4384 Port Greenock Classed 7A1
61

REPAIRS

Now done - Caulked from keel to gunwale excepting
under boottopping - Bottom sheathed with Yellow metal
on paper ~

Present Condition of the

Decks	} good	Treenails	} good	Windlass and Capstan	} good
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings	} firm	Timbers of the Frame at the openings	} where	Masts, Yards, &c.	} and
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Sails	
Planksheers		Keelsons		Anchors No. of	
Sheerstrakes	} good	Clamps and Shelves	} seen	Cables	} sufficient
Topsides		Ceiling		Hawsers and Warps	
Wales		Rudder		Standing & Running Rigging	
Plank (Bottom) and Counter	caulked	Copper <u>YM</u> When put on <u>now</u>			

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where tested

She is now in good condition, fit in ^{my} ~~any~~ opinion for the
safe conveyance of dry and perishable goods to and from
all parts of the world and to remain as Classed

The Amount of Fee.....£ : : is received by me,

Special..... 1 : 1 : -

Certificate (if required) : : :

Committee's Minute 1st December 1863

Character assigned 7A1 record YM

Charge £ 1 - 1 -



© 2021
Lloyd's Register
Foundation
LON647-0489