

*25837

REPORT of SURVEY for REPAIRS.

Change of Owners
No. 102 Survey held at London Date Feb 25 to 21 Mar 1863
on the ship "Star Queen" Master J. Cues
Tonnage 852 Built at Sunderland When built 1854
By whom built _____ Owners Pylam Bros
Port belonging to London Destined Voyage China via Cardiff
If Surveyed Afloat or in Dry Dock Fletcher's dry dock

Last Survey, No. 24230 Port London Classed 1341
1061

REPAIRS

*Now docked to sight bottom and patch metal
Bowsprit and Cope Jack yard new*

Present Condition of the

Decks <u>Good where seen</u>	Treenails <u>Good where seen</u>	Windlass and Capstan <u>22 in good & suff</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>2</u> <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>4</u> <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>at the Openings</u> <u>"</u>	Masts, Yards, &c. <u>pt new</u> <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Do Do <u>at other places</u> <u>"</u>	Sails <u>20</u> <u>"</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Anchors No. of <u>3 B. 1 S. 2 W</u> <u>"</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Cables <u>"</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>"</u>
Plank (Bottom) and Counter <u>"</u>	<u>Copper on felt</u> When put on <u>1861</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where seen

*This vessel is in good and efficient condition
eligible in my opinion to remain as classed 41*

The Amount of Fee.....£ 1 : — : — is received by me, J. Edwin Blouchman
Special..... : :
Certificate (if required) : :

Committee's Minute 1st December 1863

Character assigned 1341

