

REPORT of SURVEY for REPAIRS.

change of Owners

No. _____ Survey held at London Date Dec^r 18 62
 on the S. Morayshire Master Jos Mather
 Tonnage 788 Built at Moulmein When built 1853
 By whom built _____ Owners Gellatly &
 Port belonging to London Destined Voyage Bombay
 If Surveyed Afloat or in Dry Dock Ratcliff cross & E. S. Dock

Last Survey, No. See annexed Report Port N^o 25875 Classed 12 A 1

REPAIRS

yellow metal repaired

Present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Keelsons		Sails	
Planksheers		Clamps and Shelves		Anchors No. of	
Sheerstrakes		Ceiling		Cables	
Topsides		Rudder		Hawsers and Warps	
Wales		Copper <u>YML 61</u> When put on		Standing & Running Rigging	
Plank (Bottom) and Counter					

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where seen

This vessel is now in good condition and is eligible in our opinion to remain classed A 1

The Amount of Fee.....£ : : is received by me, Thos. W. Mawson
 Special..... : :
 Certificate (if required) : :

Committee's Minute _____ 18 _____

Character assigned _____



© 2019

Lloyd's Register
Foundation

Lon 648-0006