

25908

Recd 12.11.63
89

REPORT of SURVEY for REPAIRS.

No. _____ Survey held at London Date Oct 24th 30th 18 63
on the S. Highflyer Master Smith
Tonnage 1012 Built at London When built 1861
By whom built _____ Owners Green &
Port belonging to London Destined Voyage Sydney
If Surveyed Afloat or in Dry Dock Greens upper dock &

Last Survey, No. _____ Port _____ Classed 13 A 1

REPAIRS

Yellow metal stripped, recaulked from keel to metal line and resheathed with yellow metal on dry paper

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>IME</u> When put on <u>now</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

good where tested

This vessel is eligible in my opinion to remain classed 13 A 1

The Amount of Fee.....£ : : is received by me,

Special..... / : / : ~

Certificate (if required) : :

Committee's Minute 8th January 1864

Character assigned _____



© 2019

Lloyd's Register
Foundation

100 648 - 00 34