

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 814 Survey held at London Date Dec^r 1st 6th 1863
 on the Ship "Corea" Master J. Garry
 Tonnage 581 Built at Worthington When built 1859
 By whom built _____ Owners Bushby
 Port belonging to Worthington Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Smith's Dry Dock

Last Survey, No. 24095 Port London Classed 14 A 1

REPAIRS

How done, Caulked from the keel to the gunwale and her bottom resheathed with Yellow Metal on Paper -

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>Good</u>	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c. } <u>Good and</u>
Lower Deck Beams & Fastenings } <u>Good</u>	Ditto Ditto at other places	Sails } <u>Sufficient</u>
Planksheers	Keelsons } <u>Good</u>	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides } <u>Caulked</u>	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter <u>Caulked</u>	<u>Copper on Paper</u> When put on <u>how</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

She is now fit in my opinion to remain as classed
14 A 1.

B. Weymouth

The Amount of Fee.....£ _____ is received by me,

Special..... / : / : -

Certificate (if required) _____

Committee's Minute 22nd January 18 64

Character assigned 14 A 1



© 2019

Lloyd's Register Foundation

LCN 648-0049