

REPORT of SURVEY for REPAIRS.

25937

No. 26 Survey held at London Date Jan 4th 20th 18 64
 on the B^m Orestes Master Richard Grover
 Tonnage 193 Built at P. L. Island When built 1863
 By whom built Longworth Owners J. Sharp
 Port belonging to Shoreham Destined Voyage Coasting
 If Surveyed Afloat or in Dry Dock in West India Dock

Last Survey, No. 352 Port P. L. Isl. Classed 7 A

REPAIRS

Stores now supplied

60 fathoms $1\frac{1}{8}$ inch short link to a strain of 15-5-0 (See Table 22)
 120 " 1 inch long link stud " " " 18-0-0

Anchors	cwt	qrs	lbs	} strain applied	Tons	cwt	qrs
3 Bowers	8	1	20		10	11	0
ex stocks	8	1	17		10	10	0
	8	1	20		10	10	0
1 Stream	3	1	18				
1 Kedge	1	3	5				

Tables

60 fathoms $\frac{3}{4}$ chain
 60 " $1\frac{1}{2}$ way
 60 " $6\frac{1}{2}$ "
 65 " $4\frac{1}{2}$ "
 65 " $5\frac{1}{2}$ "

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Do Do at other places	Sails
Planksheers	Keelsons	Anchors No. of <u>3 B, 1 S, 1 K</u> see above
Sheerstrakes	Clamps and Shelves	Cables " " *
Topsides	Ceiling	Hawsers and Warps " "
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper When put on	* Cert. of Test for Anchors and Chains returned to Owner 5/2/64
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways.	

Should the Committee deem the stores supplied sufficient I beg to recommend that the figure "1" may be appended to the "A"

The Amount of Fee.....£ : 10 : is received by me, John Maxwell
 Special..... 1 : 1 : 0
 Certificate (if required) : 2 : 6

Committee's Minute 2nd February 18 64

Character assigned 7 A
 (A.P.)



© 2019

Lloyd's Register Foundation

LON 648 - 0063