

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 356 Survey held at London Date Nov 27 1863
 on the Ship "Mars" Master Henderson
 Tonnage 721 Built at Sunderland When built 1836
 By whom built _____ Owners J. Allan
 Port belonging to London Destined Voyage Madras
 If Surveyed Afloat or in Dry Dock Smith's Dry Dock

Last Survey, No. 24842 Port London Classed 13 A 1
 62

REPAIRS

How done, Caulked from the keel to the gunwale and her bottom sheathed with yellow metal on felt.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>Good</u>	Breasthooks and Stemson	Pumps
Comings } <u>Good</u>	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c. } <u>Good and</u>
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Sails } <u>Sufficient</u>
Planksheers	Keelsons	Anchors No. of
Sheerstrakes } <u>Caulked, good</u>	Clamps and Shelves	Cables
Topsides } <u>Where seen</u>	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter <u>Caulked</u>	<u>Yellow metal</u> <u>Copper on felt</u> When put on <u>How</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where tested

How in good and efficient condition, fit in my opinion to remain classed 13 A 1.

B. Weymouth

The Amount of Fee.....£ _____ is received by me,

Special..... 1 : 1 : -

Certificate (if required) _____

Committee's Minute 12th February 1864

Character assigned 13 A 1

record



© 2019

Lloyd's Register Foundation

LONG 648 - 0083