

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 621 Survey held at London Date Feb'y 17<sup>th</sup> 18<sup>th</sup> 1864  
 on the Ship Mary Spencer Master Joseph Flarty  
 Tonnage 429 Built at Whitehaven When built 1847  
 By whom built 479 Owners W. D. Boadle  
 Port belonging to Whitehaven Destined Voyage Liverpool  
 If Surveyed Afloat or in Dry Dock "Savender" Dry dock

Last Survey, No. 18014 Port Liverpool Classed 13. A. 1. Cont. in 60. 4. A. 1.

## REPAIRS

Surveyed this Vessel at the above dates, found the yellow metal sheathing all stripped off except the two upper strakes in midships and the bottom partly caulked. Examined her inside as far as practicable. (ballast being on board) at the fore end between the lower Hooks (Starboard side) discovered some defective Ceiling, the Timbers at that spot also proved bad, advised the Owner (who was present) to renew them and make all good, which he however has declined to do at this Port, and she has been undocked to be taken round to Liverpool.

### Present Condition of the

|                               |                                      |                            |
|-------------------------------|--------------------------------------|----------------------------|
| Decks                         | Treenails                            | Windlass and Capstan       |
| Waterways                     | Breasthooks and Stemson              | Pumps                      |
| Comings                       | Transoms, Pointers, and Crutches     | Boats                      |
| Upper Deck Beams & Fastenings | Timbers of the Frame at the openings | Masts, Yards, &c.          |
| Lower Deck Beams & Fastenings | Ditto Ditto at other places          | Sails                      |
| Planksheers                   | Keelsons                             | Anchor No. of              |
| Sheerstrakes                  | Clamps and Shelves                   | Cables                     |
| Topsides                      | Ceiling                              | Hawsers and Warps          |
| Wales                         | Rudder                               | Standing & Running Rigging |
| Plank (Bottom) and Counter    | Copper When put on                   |                            |

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

We are of opinion until this Vessel has been efficiently repaired her Character should be suspended.

The Amount of Fee.....£ : : is received by me, Samuel Resious.  
at Liverpool  
W. J. M. M. M.

Special..... / : / : 25/5/64

Certificate (if required) : :

Committee's Minute 23<sup>rd</sup> February 1864  
1<sup>st</sup> March 1864

Character assigned

LON 648-0105



© 2019  
 Defensed  
 Lloyd's Register  
 Foundation