

REPORT of SURVEY for REPAIRS.

No. 246 Survey held at London Date April 17th 18 63
 on the S "Phaeton" Master _____
 Tonnage 416 Built at Whitehaven When built 1859
 By whom built Kennedy Owners W. Turner
 Port belonging to Dumfries Destined Voyage _____
 If Surveyed Afloat or in Dry Dock in Bridge & London Docks

Last Survey, No. 1802 Port Whitehaven Classed 13 A1
59.

REPAIRS

Stripped Yellow metal sheathing caulked from Keel to Wales and re-sheathed with Yellow metal over felt.

Renewed part deck with English Oak and Yellow Pine.

Present Condition of the

Decks	<u>Good</u>	Treenails	<u>where seen Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	"	Breasthooks and Stemson	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame	<u>where seen</u>	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Keelsons	<u>where seen</u>	Sails	"
Planksheers	"	Clamps and Shelves	"	Anchors	No. of <u>3 B, 1 S, 1 K</u>
Sheerstrakes	"	Ceiling	"	Cables	"
Topsides	"	Rudder	"	Hawsers and Warps	"
Wales	"	Copper <u>F & Y M</u>	When put on <u>1863</u>	Standing & Running Rigging	"
Plank (Bottom) and Counter	"				

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. where tested Good

Is now in good and efficient condition and is in our opinion fit to remain as classed.

The Amount of Fee.....£ _____ is received by me,

Special..... / : / : 0 M

Certificate (if required) : :

Committee's Minute 15th March 18 63

Character assigned 13 A1

John Maxwell
Thos. W. Wain



© 2019

Lloyd's Register Foundation

LOW 648 - 0146

Phactn



© 2019

Lloyd's Register
Foundation