

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 200 on the **BK "Persia"** Survey held at **London** Date **Feb^y 22nd** 18 **64**
 Tonnage **526** Built at **Scarb^o** Master **John W. Chaturain**
 By whom built **Jindall** Owners **Jindall**
 Port belonging to **Scarb^o** Destined Voyage **Quebec**
 If Surveyed Afloat or in Dry Dock **in Commercial Dock**

Last Survey, No. **24373** Port **London** Classed **12 * A1**
 REPAIRS **C4 12.61 SS.64**
SS 54

Renewed Waterways on each side of American Red Pine; nearly entire new deck from Windlass aft of Yellow pine; after hatch comings of American Oak and caulked from waterway seams inclusive to middle line

Present Condition of the

Decks pt new Good	Treenails where seen Good	Windlass and Capstan Good
Waterways new "	Breasthooks and Stemson "	Pumps "
Comings pt new "	Transoms, Pointers, and Crutches "	Boats "
Upper Deck Beams & Fastenings where seen "	Timbers of the Frame at the openings "	Masts, Yards, &c. "
Lower Deck Beams & Fastenings "	Ditto Ditto at other places "	Sails "
Planksheers "	Keelsons "	Anchors No. of 3 B, 1 S, 1 K
Sheerstrakes "	Clamps and Shelves "	Cables "
Topsides "	Ceiling "	Hawsers and Warps "
Wales "	Rudder "	Standing & Running Rigging "
Plank (Bottom) and Counter "	Copper F.D. 61 When put on "	
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. where seen Good	

Is now in good condition fit to carry dry cargoes and is in our opinion fit to be classed **A1** which character the Owner is willing to accept.

The Amount of Fee.....£ / : - : - is received by me,

Special..... / : / : 0

Certificate (if required) : :

Committee's Minute **8th April** 18 **64**

Character assigned **A1** **condition** **work** **repaired**



© 2019

Lloyd's Register Foundation

LOUGHRAN-0183

Persa



© 2019

Lloyd's Register
Foundation