

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 388 on the **B8 "Truant"** Survey held at **London** Date **Feb. 27th to March 18th 64** Master **Jones**
 Tonnage **141** Built at **Aberystwith** When built **1840**
 By whom built **✓** Owners **Jones**
 Port belonging to **Aberystwith** Destined Voyage **Penarth**
 If Surveyed Afloat or in Dry Dock **in West India Dock**

Last Survey, No. **556** Port **Aberystwith** Classed **12 A1** Rest **58 8 yrs**

REPAIRS

Upon making survey on this vessel we found Rides Keelson and ceiling from upper part of Bilges downwards very defective, sent notice to the owners recommending their renewal which has not been done and she has sailed from this port for Penarth where she will take in a cargo of timber for Aberystwith and it is then proposed to carry out the repairs suggested.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Sails
Planksheers	Keelsons	Anchor No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

Under the above mentioned circumstances we beg respectfully to leave the character of this vessel in the hands of the Committee.

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute **8th April** 18 **64**

Character assigned

Expense Character

Notice to owners
2.8/4/64



© 2019

Lloyd's Register Foundation

Grant

REPORT OF THE LLOYD'S REGISTER



© 2019

Lloyd's Register
Foundation