

Change of Owners & Damages - 26078 REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** Survey held at London Date 13th Mar to Apr. 3rd 1864
341 on the Brig Celestial late Alexander Master Lt. J. Allen
 Tonnage 207 Built at Prince E. Island When built 1862
 By whom built _____ Owners Dessie
 Port belonging to Surinam Destined Voyage Nickerie
 If Surveyed Afloat or in Dry Dock Mess^{rs} Fletcher's Dry Dock & W. J. Dock

Last Survey, No. 25486 Port London Classed Y.P. 1st

REPAIRS

Now done, the yellow metal sheathing stripped off the bottom, the keel hung in shores and caulked from the keel to the Centre of the upper deck. The Head Rails, Beathing to the Head, Dead Timbers, and the Cross Pieces to the Head renewed -

Five Pairs of hanging knees of Iron added to the upper deck, and three Pairs of Iron Knee Riders to the Bold Beams -

Present Condition of the

Decks

Waterways } Caulked
 Comings }
 Upper Deck Beams & Fastenings } firm
 Lower Deck Beams & Fastenings }
 Planksheers }
 Sheerstrakes } Caulked
 Topsides }
 Wales }

Treenails

Breasthooks and Stemson
 Transoms, Pointers, and Crutches
 Timbers of the Frame at the openings
 Ditto Ditto at other places
 Keelsons } Good where
 Clamps and Shelves } seen
 Ceiling
 Bigger } Yellow Metal
 Copper } on felt When put on now

Windlass and Capstan

Pumps
 Boats
 Masts, Yards, &c. } Good and
 Sails } sufficient
 Anchors No. of
 Cables
 Hawser and Warps
 Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where seen

She is now in good and efficient condition, fit in my opinion to remain as classed Y.P. 1.

B. T. Wainwright

The Amount of Fee.....£ / : : is received by me,

Special..... / : / :

Certificate (if required) : : :

Committee's Minute 12th April 1864

Character assigned 7th 1st record & M



© 2019

Lloyd's Register Foundation

LN 648-0186