

26082
IRS.

Dec 11. 4. 64

REPAIRS

Certificates produced for the following Anchor and Chain Cable tests -

Chains -
180 Link $1\frac{13}{16}$ - Lested to 59.0
120 - " - $1\frac{7}{8}$ - " - - 63.5

300 Link

Present Condition of the

Windlass and Capstan }
Pumps } food
Boats }
Masts, Yards, &c. } food and
Sails } sufficient
Anchors No. of 3 B. 1 S. 2 H
Cables 30 0 Lathum
Hawsers and Warps } food &
Standing & Running Rigging } sufficient

General Observations and Opinion,

Her Anchors are lighter than required by the Table, but heavier than the minimum weight allowed by the last note of it - and Testing Certificates have been produced showing that they have been subjected to a greater strain than prescribed by the Rules - A portion of her chains it will be seen is longer than required for her Tonnage, and the whole of them have been fully tested - I beg to recommend her

The Amount of Fee.....£ 1/- is received by me, for the 7th 1 class.

Special..... ३ : ३ :

Certificate (if required) — : — : —

Committee's Minute 12th April 1861

Character assigned

record of

Lloyd's Register
Foundation
2016-2019

2016-0190