

26181 REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 533 Survey held at London Date Feb to March 4th 1864
 on the Ship "Subilee" Master J. Grant
 Tonnage 764 Built at Worthington When built 1837
 By whom built _____ Owners J. Brodie
 Port belonging to London Destined Voyage China
 If Surveyed Afloat or in Dry Dock Ship^{rs} Jennings' Dry Dock & E. J. Beck

Last Survey, No. 25759 Port London Classed 14 F 1
 REPAIRS How done, her yellow metal sheathing renewed on Fell-
and her bottom Caulked -

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Budder <u>Yellow metal</u>	Standing & Running Rigging
Plank (Bottom) and Counter <u>Caulked</u>	Copper <u>on Fell</u> When put on <u>how</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where tested

She is in good Condition. fit in my opinion to
remain as classed 14 F 1.

B. Weymouth

The Amount of Fee.....£ _____ is received by me,

Special..... 1 : 1 : - AB

Certificate (if required) _____

Committee's Minute 7th June 1864

Character assigned 14 F 1 second fm

MA

