

ANNUAL SURVEYS.

26203

Recd 16/6/64

No. 983 Survey held at London Date May 31st 18 64
 on the "Asterope" Master Adam Stuart
 Tonnage 601 Built at Aberdeen When built 1859
 By whom built Hall Owners Parker & Co
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock in West India docks

Last Survey, No. 26135 Port of London. Classed 13 A1
~~5.64~~

The present Condition of the

Decks when seen Good
 Waterways _____
 Comings _____
 Upper Deck Beams & Fastenings _____
 Lower Deck Beams & Fastenings _____
 Planksheers _____
 Sheerstrakes _____
 Topsides _____
 Wales _____
 Plank (Bottom) and Counter _____

Treenails when seen Good
 Breasthooks and Stemson not seen
 Transoms, Pointers, and Crutches _____
 Timbers of the Frame at the Openings _____
 Do Do at other places _____
 Keelsons _____
 Clamps and Shelves when seen Good
 Ceiling _____
 Rudder _____
 Copper YM When put on 1862

Windlass and Capstan Good
 Pumps _____
 Boats _____
 Masts, Yards, &c. _____
 Sails _____
 Anchors No. of 3 B, 1 S, 2 K
 Cables _____
 Hawser and Warps _____
 Standing & Running Rigging _____

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways when seen Good

Is now in good and efficient condition and is in my opinion fit to remain as classed

Committee's Minute 21st June 18 64
 Character assigned 13 A1

John Maxwell

Certificate (if required)

No. 326 Survey held at London Date June 1st 18 64
 on the 326 "Dunkeld" Master D. Fraser
 Tonnage 378 Built at Pictou Nova Scotia When built 1862
 By whom built Mc Donald Owners Mc Donald
 Port belonging to Pictou Destined Voyage _____
 If Surveyed Afloat or in Dry Dock on Lloyd's Slipway Greenwich

Last Survey, No. 606 Port of St. John. Classed 4 A1
~~62~~

The present Condition of the

Decks when seen Good
 Waterways _____
 Comings _____
 Upper Deck Beams & Fastenings _____
 Lower Deck Beams & Fastenings _____
 Planksheers _____
 Sheerstrakes _____
 Topsides _____
 Wales _____
 Plank (Bottom) and Counter _____

Treenails when seen Good
 Breasthooks and Stemson _____
 Transoms, Pointers, and Crutches _____
 Timbers of the Frame at the Openings _____
 Do Do at other places not seen
 Keelsons _____
 Clamps and Shelves when seen Good
 Ceiling _____
 Rudder _____
 Copper YM When put on 1863

Windlass and Capstan Good
 Pumps _____
 Boats _____
 Masts, Yards, &c. _____
 Sails _____
 Anchors No. of 3 B, 1 S, 1 K
 Cables _____
 Hawser and Warps _____
 Standing & Running Rigging _____

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways when seen Good

Painted yellow metal sheathing
Is now in good and efficient condition and is in my opinion fit to remain as classed

Committee's Minute 21st June 18 64
 Character assigned 4 A1

John Maxwell

© 2019

Certificate (if required).

LONDON - D302

THE LLOYD'S REGISTER

Handwritten signature

