

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 370 Survey held at London Date May 6<sup>th</sup> 18 64  
 on the "Clarendon" Master J. King  
 Tonnage 656 Built at Sunderland When built 1856  
 By whom built ✓ Owners J. Holmes  
 Port belonging to London Destined Voyage China  
 If Surveyed Afloat or in Dry Dock in Eastern & West India Docks

Last Survey, No. 24487 Port London Classed 13 A1  
2.62

## REPAIRS

Stripped Yellow metal sheathing, took down and re-fitted an Iron hanging knee to Lower deck; renewed two upper deck beam ends and one length of Waterway on Port side with Teak; about 350 feet of deck of Yellow Pine; Windlass unhooked, stripped, examined and additionally hooped; caulked from keel to metal line and re-sheathed with Yellow metal over felt.

### Present Condition of the

Decks <u>pt new</u> <u>Good</u>	Treenails <u>when seen</u> <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>"</u> <u>"</u>	Breasthooks and Stemson <u>"</u> <u>"</u>	Pumps <u>"</u>
Comings <u>"</u> <u>"</u>	Transoms, Pointers, and Crutches <u>"</u> <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u> <u>"</u>	Timbers of the Frame at the openings <u>"</u> <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u> <u>"</u>	Ditto Ditto at other places <u>"</u> <u>"</u>	Sails <u>"</u>
Planksheers <u>"</u> <u>"</u>	Keelsons <u>"</u> <u>"</u>	Anchors No. of <u>3 B, 1 S, 1 K.</u>
Sheerstrakes <u>"</u> <u>"</u>	Clamps and Shelves <u>"</u> <u>"</u>	Cables <u>"</u>
Topsides <u>"</u> <u>"</u>	Ceiling <u>"</u> <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u> <u>"</u>	Rudder <u>"</u> <u>"</u>	Standing & Running Rigging <u>"</u>
Plank (Bottom) and Counter <u>"</u> <u>"</u>	Copper <u>F. &amp; Y. M.</u> When put on <u>1864</u>	
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>where tested</u> <u>Good</u>	

Is now in good and efficient condition and is in my opinion fit to remain as classed

The Amount of Fee.....£ 2 : - : is received by me, John Maxwell

Special..... 1 : 1 : 0

Certificate (if required) : 5 : -

Committee's Minute 28<sup>th</sup> June 18 64

Character assigned 13 A1

record repair



© 2019

Lloyd's Register Foundation

LON 648 - 0 308