

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. *418* No. *25645* Survey held at *London* Date *May 30th* 18*64*
 on the *Ship Wynaud* Master *C. P. Jones.*
 Tonnage *596* Built at *London* When built *1854.*
 By whom built _____ Owners *W. H. Tindall*
 Port belonging to *London* Destined Voyage *Ceylon.*
 If Surveyed Afloat or in Dry Dock *"Nelson" dry dock*

Last Survey, No. *25645* Port *London.* Classed *13. A. 1.*
 REPAIRS 63

At this date Stripped off the whole of the Yellow Metal Sheathing. Caulked the outside from the Keel to three seams above the Wales. -

Resheathed with yellow metal on felt up to the height of 16 ft 6 ins. -

Present Condition of the

Decks	<i>in good condition</i>	Treenails	<i>good</i>	Windlass and Capstan	<i>in good order</i>
Waterways	"	Breasthooks and Stemson	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	Sails	"
Planksheers	"	Keelsons	"	Anchors No. of <i>3</i>	"
Sheerstrakes	"	Clamps and Shelves	"	Cables	"
Topsides	"	Ceiling	"	Hawsers and Warps	"
Wales	"	Rudder <i>effick</i>	"	Standing & Running Rigging	"
Plank (Bottom) and Counter	"	<i>Copper Yellow metal on felt</i> When put on <i>now</i>			
General Observations and Opinion,		Caulking of Bottom, Deck, & Waterways. <i>good</i>			

I am of opinion this Vessel is entitled to remain as Class'd *13. A. 1.*

Samuel Presons.

The Amount of Fee.....£ : : is received by me,

Special..... / : / : *W*

Certificate (if required) : :

Committee's Minute *5th July* 18*64*

Character assigned *13 A 1*



© 2019

Lloyd's Register Foundation

lon 648-0316