

REPORT of SURVEY for REPAIRS.

No. in Book. No. 20277/20174
 Reg. 1 65 Survey held at London Date July 16th 21st 1864
 on the Barque "Flying Fish" Master G. Taylor
 Tonnage 393 Built at Sunderland When built 1858
 By whom built Owners Javan Bros.
 Port belonging to London Destined Voyage West Indies
 If Surveyed Afloat or in Dry Dock Bridge Dry Dock & London Dock

Last Survey, No. 24876 Port London. Classed 13 A. 1.
 REPAIRS Now done, the Copper Sheathing patched
 The middle line and the Planks cleared
 the timbers lifted, and the Floors, Keelsons &c &c examined.

Present Condition of the

Decks	} good	Treenails	} good	Windlass and Capstan	} good
Waterways		Breasthooks and Stemson		Pumps	
Omings	} firm	Transoms, Pointers, and Crutches	} where	Boats	} and
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	} good	Ditto Ditto at other places	} seen	Sails	} sufficient
Planksheers		Keelsons		Anchors No. of	
Beerstrakes	} where	Clamps and Shelves	} ?	Cables	} ?
Upsides		Ceiling		Hawsers and Warps	
Tales	} seen	Rudder	} 1862	Standing & Running Rigging	} ?
Plank (Bottom) and Counter		Copper on felt When put on			

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. good where seen

She is now in good condition and fit in our opinion to remain as classed 13 A. 1

The Amount of Fee.....£ is received by me,

Special..... 1: 1: - } \$

Certificate (if required) : 5: - }

Committee's Minute 29th July 1864

Character assigned 13 A. 1



Charge £ 1 -



© 2019

Lloyd's Register Foundation

LOV648-0370



© 2019

Lloyd's Register
Foundation