

REPORT of SURVEY for REPAIRS.

26377 ~~26377~~
 Date Sep 6th to Sept 24th 1864
 Master A. Duin
 Owners J. Phillips

No. in Reg. Book. No. 194 Survey held at London
 on the Ship "Cruwell"
 Tonnage 1000 Built at Starwich When built 1854
 By whom built _____ Owners J. Phillips
 Port belonging to London Destined Voyage Melbourne
 If Surveyed Afloat or in Dry Dock Messrs Green's Dry Dock & East India Dock

Last Survey, No. 25793 Port London Classed 12 A.1.

REPAIRS Now done, the yellow metal sheathing stripped off, hung in shores and the bottom faulted and resheathed with yellow metal on felt. The butts of the wales and topsides - the lower deck, and the waterways and plank-sheer, and butts and comings of upper deck faulted.

Present Condition of the

Decks <u>butts faulted</u>	Treenails	Windlass and Capstan
Waterways <u>caulked</u>	Breasthooks and Stemson	Pumps
Comings <u>do</u>	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Sails
Plank-sheers <u>faulted</u>	Keelsons	Anchors No. of
Sheerstrakes <u>butts faulted</u>	Clamps and Shelves	Cables
Topsides <u>do</u>	Ceiling	Hawsers and Warps
Wales <u>do</u>	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter <u>caulked</u>	<u>Y.M. & P.</u> When put on <u>now</u>	

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. good where tested

She is now in good and efficient condition, fit in our opinion for the safe conveyance of dry cargoes to and from all parts of the world and to remain as classed 12 A.1

The Amount of Fee.....£ : : is received by me,
 Special..... 1 : 1 : -
 Certificate (if required) : 5 : -

Committee's Minute 30th September 1864

Character assigned 12 A.1

Charge £1. - 1/6