

REPORT of SURVEY for REPAIRS.

26467

No. in Reg. Book. **No.** 194 Survey held at London Date Nov^r 3rd 18 64
 on the B^e "Bermundsey" Master F. J. Le. Little
 Tonnage 445 Built at Whitby When built 1841
 By whom built Port Natal Owners Miller + Daconb.
 Port belonging to London Port Natal Destined Voyage
 If Surveyed Afloat or in Dry Dock Bullhead dock + London Dock
Sen 110.7 Bvd. 26.5 Dpt 19.9 Register produced
 Last Survey, No. 24557 Port London Classed A. 1
3.62

REPAIRS

The yellow metal sheathing stripped, the jule
 stern post renewed, the lower piece of gripe
 rebolted, the vessel recaulked over all and
 resheathed with yellow metal over felt -
 About ^{eigh} ten planks of deck on each side
 renewed with Red Pine.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings <u>Where</u>	Masts, Yards, &c. <u>Good +</u>
Lower Deck Beams & Fastenings <u>Where</u>	Ditto Ditto at other places <u>seen</u>	Sails <u>sufficient</u>
Planksheers <u>seen</u>	Keelsons	Anchors No. of
Sheerstrakes <u>good</u>	Clamps and Shelves	Cables
Topsides	Ceiling <u>good</u>	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>Now</u> When put on <u>now</u>	
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>good where tested</u>	

This vessel appears eligible in our
 opinion to remain as classed

The Amount of Fee.....£ 1 : - : is received by me, Thos. W. Wain
 Special..... 2 : 2 : - Harding
 Certificate (if required) : 5 : -
 Committee's Minute 8th November 18 64
 Character assigned A. 1
Record repair