

21554

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 297 Survey held at London Date November 7th 1864
 on the Br. * "Aleyone" Master W. Harvey
 Tonnage 371 Built at Sunderland When built 1854
 By whom built _____ Owners G. Podd
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock New Crane Dock.

Last Survey, No. 25342 Port London Classed G. A. I.
 2.63.

REPAIRS now done :

One lower-hold-beam renewed with Dantzic Oak; two pairs of vertical, and six pairs of diagonal, Iron Riders added, four pairs of the latter extending from the upper deck-shelf to the floorboards; the yellow Metal sheathing stripped, the Vessel recaulked from keel to sixth beam of deck, and re-sheathed with yellow Metal over felt.

Present Condition of the

Decks <u>Good where seen</u>	Treenails <u>Good where seen</u>	Windlass and Capstan <u>Good</u>
Waterways "	Breasthooks and Stemson "	Pumps "
Comings "	Transoms, Pointers, and Crutches "	Boats "
Upper Deck Beams & Fastenings "	Timbers of the Frame at the openings "	Masts, Yards, &c. "
Lower Deck Beams & Fastenings "	Ditto Ditto at other places "	Sails "
Planksheers "	Keelsons "	Anchors No. of <u>Sufficient</u>
Sheerstrakes "	Clamps and Shelves "	Cables "
Topsides "	Ceiling "	Hawsers and Warps "
Wales "	Rudder <u>to G.M.</u> When put on <u>Now</u>	Standing & Running Rigging "
Plank (Bottom) and Counter "		
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>Good where tested.</u>	

This Vessel appears to be in good and efficient condition, and is eligible, in our opinion, to remain as classed - G. A. I.

The Amount of Fee.....£ : : is received by me,

Special..... 1 : 1 : 0

Certificate (if required) : :

Committee's Minute 3rd January 1865

Character assigned G. A. I.

P. J. Reed
Thos. M. Wain



© 2019

Lloyd's Register
 Foundation
 LON649-0140